



**PASEGURAHAN NG MGA NAGLILINGKOD SA PAMAHALAAN
(GOVERNMENT SERVICE INSURANCE SYSTEM)**
Financial Center, Pasay City, Metro Manila 1308

**GSIS BIDS AND AWARDS COMMITTEE
FOR INFRASTRUCTURE AND INFORMATION TECHNOLOGY**

Project Title: **Comprehensive Maintenance of Cisco Network Equipment in Home and Branch Offices**

Bid Bulletin No. 1
31 March 2017

This bid bulletin is issued to amend and modify items in the Bidding Documents for the **Comprehensive Maintenance of Cisco Network Equipment in Home and Branch Offices**. This shall form an integral part of the Bidding Documents.

1. SECTION VII. TECHNICAL SPECIFICATIONS

From	To
<p>Other Requirement</p> <p>The service provider must be an authorized distributor, reseller or partner of Cisco Network Equipment that are similar to that of GSIS.</p>	<p>Other Requirements</p> <ol style="list-style-type: none"> 1. The service provider must be an authorized distributor, reseller or partner of Cisco Network Equipment that are similar to that of GSIS. 2. The Service Provider must have the following locally available certified, qualified and experienced personnel to provide technical support during the maintenance period. <ul style="list-style-type: none"> o Cisco Certified Network Professional o Cisco Certified Network Associate

**2. ANNEX C OF THE BIDDING DOCUMENTS
LIST OF GSIS BRANCHES – TECHNICAL SUPPORT RESPONSE TIME**

From

HOME/BRANCH OFFICE	Address
Pasig Extension Office	Upper Ground Floor, JNCV Bldg., Pasig Blvd. cor Rosemary Lane, Pasig City 1600
Tandag Extension Office	Capitol Rd, Brgy. Telaje, Tandag City

To

HOME/BRANCH OFFICE	Address
Pasig Extension Office	3F Unit Elements@Rosemarie Building, Pasig Boulevard corner Rosemarie Lane, Brgy. Kapitolyo, Pasig City
Tandag Extension Office	JTP Realty Building, Provincial Capitol Road, Telaje, Tandag City, Surigao Del Sur

**3. ANNEX D OF THE BIDDING DOCUMENTS
NETWORK EQUIPMENT SERIAL NUMBERS**

1	Cisco Catalyst 6509-E Switch
	<ul style="list-style-type: none"> - SMC16430012 - SMC1643001E

2	Cisco Catalyst 3750X-24T-S Switch
	<ul style="list-style-type: none"> - FDO1635Z05T - FDO1733R19L - FDO1439K270 - FDO1736R0L6 - FDO1736Z0RZ - FDO1736R0LB - FDO1816Z3A5 - FDO1717P3BY - FDO1721Z2EC - FDO1624V1Q1 - FDO1721Z2C5 - FDO1717P3C2 - FDO1717P3EF - FDO1541Z0LB - FDO1721Z2EV - FDO1721R2B8 - FDO1544Z09J - FDO1618Z0M2 - FDO1736R0L8 - FDO1736R0L9 - FDO1717Z2W3 - FDO1526R029

3	Cisco Catalyst 2960S-48FPS-L Switch
	<ul style="list-style-type: none"> - FOC1642X3PN - FOC1642X3PW - FOC1643W1X0 - FOC1643W1UD - FOC1643W1VF - FOC1642Z36T - FOC1642Z36W - FOC1642X3PR - FOC1643Z3PP - FOC1642X3PV - FOC1643W1UB - FOC1642Z30P - FOC1642Z383 - FOC1642Z36Q - FOC1642X3PA - FOC1642X3PT - FOC1642X3PL - FOC1643Z3Q4 - FOC1642Z36K - FOC1642X3PS

4	Cisco Catalyst 2960S-48TS-L Switch
	<ul style="list-style-type: none"> - FOC1642W1UT - FOC1642W1UD - FOC1642W1U1 - FOC1642W1TW - FOC1642W1QT - FOC1642W1QW - FOC1642W1LZ - FOC1642W1QY - FOC1641Z1GV - FOC1642W1U4 - FOC1642W1UV - FOC1642W1RY - FOC1642W1LU - FOC1642W1TJ - FOC1642W1M7 - FOC1642W1PR - FOC1642W1U9 - FOC1642W1PS

Handwritten initials and signatures:
A B
P
PS

- FOC1642W1LS	- FOC1642W1TS	- FOC1642W1S9
- FOC1642W1UJ	- FOC1642W1TK	- FOC1641Z1BA
- FOC1642W1UW	- FOC1642W1UF	- FOC1642W1TU
- FOC1642W1UB	- FOC1642W1TL	- FOC1642W1LT
- FOC1642W1LN	- FOC1642W1UC	- FOC1642W1U0
- FOC1642W1TP	- FOC1642W1LV	- FOC1642W1UE
- FOC1642W1TV	- FOC1642W1UG	- FOC1642W1LQ
- FOC1642W1LP	- FOC1612Z271	- FOC1642W1TQ
- FOC1642W1Q6	- FOC1642W1S2	- FOC1642W1R3
- FOC1642W1LL	- FOC1642W1TM	- FOC1642W1TN

5 Cisco Catalyst 2960S-24TS-L Switch		
- FOC1635Z1GX	- FOC1642Z4CV	- FOC1642Z4VN
- FOC1642Z43X	- FOC1635Z1LW	- FOC1642Z4UW
- FOC1635Z1PS	- FOC1642X5CH	- FOC1642Z44C
- FOC1642Z4U1	- FOC1642X5CS	- FOC1642Z4C8
- FOC1635Z1M9	- FOC1635Z16J	- FOC1642Z4C3
- FOC1642Z4VS	- FOC1642Z4F5	- FOC1642Z43Y
- FOC1642Z440	- FOC1635Z1KH	- FOC1642X5CP
- FOC1642Z4VK	- FOC1628X3J1	- FOC1635Z1N2
- FOC1635Z1M5	- FOC1642Z4F6	- FOC1635Z1LL
- FOC1642Z4C4	- FOC1635Z1GD	- FOC1642Z43T
- FOC1642Z4V7	- FOC1635Z1M3	- FOC1810Z1H9
- FOC1643W2FY	- FOC1642Z4RP	- FOC1635Z1GP
- FOC1642Z4C6	- FOC1635Z1GF	- FOC1642Z4C9
- FOC1642Z4FF	- FOC1635Z1GK	- FOC1635Z1G4
- FOC1642Z445	- FOC1635Z1M1	- FOC1642Z4VU
- FOC1642Z446	- FOC1635Z1F9	- FOC1642Z4CB
- FOC1635Z1N7	- FOC1635Z1SM	
- FOC1642X5CT	- FOC1642Z442	

6 Cisco Catalyst 2960X-24TS-L Switch	
- FOC1741S21A	
- FOC1741S22W	
- FOC1741S28S	

7 Cisco Small Business SG300-20 Switch		
- PSJ152501ZO	- PSJ152501YO	- PSJ152501Z8
- PSJ152501ZN	- PSJ152501YM	- PSJ152501Z6
- PSJ152501ZM	- PSJ152501ZQ	- PSJ152501Z5
- PSJ152501ZL	- PSJ152501ZW	- PSJ152501ZU
- PSJ152501YN	- PSJ152501ZV	- PSJ152501ZT
- PSJ152501YL	- PSJ152501Z7	

Handwritten signature and initials in the bottom right corner of the page.

8	Cisco 3945 Router
	<ul style="list-style-type: none"> - FTX1648AM1G - FTX1648AM1B - FTX1648AM1E - FTX1648AM1D

9	Cisco 3925 Router
	<ul style="list-style-type: none"> - FGL174211CF

10	Cisco 2911 Router
	<ul style="list-style-type: none"> - FGL16441195 - FGL1644119B - FGL1644119D - FGL1644119E - FGL16441194 - FGL1644119J - FGL1644119F - FGL1644119C - FTX1703ALEF - FGL16441198 - FGL16441197 - FGL151712UM - FGL1644119A - FGL16441196 - FGL16441190 - FGL1515116C - FGL164411VD - FGL164411VB - FGL164411VC - FGL164411V0 - FGL1741104N - FTX1712AKTP - FGL164411VU - FGL164411VN - FGL164411UL - FGL164411VM - FGL164411VP - FGL164411UX - FGL164411UZ - FGL164411V3 - FGL164411VG - FGL164411VH - FGL164411VT - FTX1610AJNC - FGL164411UY - FGL164411V2 - FGL164411UT - FGL164411VS - FGL164411V6 - FGL164411VJ - FGL164411UV - FGL164411UP - FGL164411VL - FGL164411VE - FGL164411UW - FGL164411UQ - FJC1929A0G9 - FGL164411V9 - FTX1751AH9D - FTX1826AH8F - FGL164411UN - FGL164411VK - FGL164411V7 - FGL164411UM - FGL164411UR - FTX1553AHN1

Note: Above serial numbers might change due to current maintenance contract.

For the guidance and information of all concerned.

fv: **VP EDUARDO V. FERNANDEZ**
 Chairperson
 GBAC for Infrastructure and Information Technology

D *PS* *f* *W*